



# VERSION 6.4 RELEASE NOTES

## New Features, Changes and Enhancements

These release notes describe the features, changes, and enhancements that are in FieldLink v6.4.

### Bug Fixes

RPT WiFi Connection crashes
TID, TC and License ID changes when working on controller with Subscription license
Grid setup informational toast is suppressed by Joystick controls
Measured label is not present for the measured origin point in Sloping plane
Out of range tilt not handled properly
TFLX in Trimble Connect - View only Design Point and Control Point
Remove 30mm checkbox for custom prism
PDF import fails when importing from Trimble Connect
Import PDF: Import button disables at specific scenarios
Unable to convert TFL file containing duplicate point names
In VISION, while in LASER MODE if the "Overview" camera zoom button is pressed, EDM unexpectedly changes to PRISM MODE
Fast mode option isn't restricted to 30m range
Model data CAPITAL .ext import bug
Crashing while renaming layer in a specific scenario

### Improvements and Features

Support for Trimble Ri total station ( <i>refer to user guide for instructions</i> )
Support for Trimble Ri subscription configurations
WiFi Band selection for Trimble Ri ( <i>restart of Ri required after change</i> )
RTS573 - Allow LASER (DR) measurements when using an RTS573 with the 'Tape Measure Tool' and 'Benchmark Transfer Tool'
Metric mode supports metric pressure settings
Change the Subscription License Timeout/Check In from 30 Days to 90 Days

## Supported Hardware, Firmware and Operating System

This version of FieldLink software works with the following and firmware combinations:

- RTS573, RTS655, RTS673 - Firmware: C10.11.1
- RTS771, RTS773, RTS873 - Firmware: B3.11.1
- Ri - Firmware: 3.2.235
- SPS610, SPS710 - Firmware: C10.11.1
- RPT600 - Firmware: R1.1.28
- R8s - Firmware: 5.50
- SPS986 - Firmware: 6.10 (Package includes 5.50 & 6.10)
- X7 - Firmware: R2.4.102

**Note:** The firmware can be installed from Trimble Installation Manager or your local service provider. To install the new firmware, follow the instructions given by the firmware update tool. For best results, connect your PC directly to the instrument via the USB cable.

This version of FieldLink software works with the following controllers:

- Trimble T100 (Windows OS updates ongoing via Microsoft)
- DTR301Y 10.1" Tablet (Windows OS updates ongoing via Microsoft)
- Trimble T10 (Windows OS updates ongoing via Microsoft)
- Panasonic FZ-M1 (Windows OS updates ongoing via Microsoft)
  - no scan module support

This version of FieldLink software works with the following Windows OS:

- Windows 11 (only recommended on PC for now)
- Windows 10 (PC, T10, T100, and DTR301Y)

## Languages

This release is available in the following languages:

English - German - French - Dutch - Finnish - Swedish - Italian - Spanish - Portuguese - Japanese - Korean - Chinese

## Upgrade Procedure

Upgrades are available via the Trimble Installation Manager (TIM). Please contact your sales rep if you need to renew your Service Software and Maintenance (SSM) to get the latest upgrade(s).

**Note:** Trimble FieldLink v5.0 and above uses a .TRB model data file format. To continue using jobs containing model data from Trimble Field Link version 4.6 and prior, the original model data must be available in either DWG, DXF, SKP, IFC or PDF. Proceed with installation only if original model data is available or can be obtained for all active jobs.

### Legal Notices

Trimble Inc., Building Construction Field Solutions, 10368 Westmoor Drive, Westminster, Colorado 80021 USA  
[www.trimble.com](http://www.trimble.com) 800-361-1249 (toll-free in the USA) +1-937-245-5154 Phone

### Copyright and Trademarks

© 2022, Trimble Inc. All rights reserved.

Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries.

Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.