

The X7 Scanner's firmware should always be updated to match the version of FieldLink that is installed on the tablet. Please see the chart below to make sure that the firmware matches the software correctly:

X7 FieldLink - Firmware Update List	
FieldLink Version	X7 FW Version
6.5	R2.4.102
6.4	R2.4.102
6.3	R2.4.5
6.2	R2.3.22
6.1	R2.3.22
6	R2.2.103
5.9	R2.1.205
5.8	R2.1.11
5.7	R2.1.4